# AS5610-52X Data Center Switch Release Note Version 2016.08.00.02-2016.09.19.00

#### 1.0 Introduction

AS5610-52X consists of 48 10G SFP+ ports and 4 40GbE QSFP+ ports. The dimensions of the AS5610-52X are 1 RU high, 438.4 mm wide and 473mm deep. AS5610-52X includes two AC or DC load-sharing, 1+1 redundant power supplies, and one fan-tray module with integral 3+1 redundant fans. The power supplies and fan module are hot swappable Field Replaceable Units. Both the power supplies and the fan-tray module are available in front-to-back or back-to-front SKUs. The switch can be managed either by in-band management via the network remotely, or out-of-band management via the console port or Ethernet management ports (both RJ45) locally.

#### 2.0 Release Content

- 1. ONIE Installer Ver. 2016.08.00.02, 2016/09/19
- 2. Bootloader Ver. 3.0.3.13, 2016/09/19
- 3. Diagnostic Ver. 1.0.0.0, 2015/01/29
- 4. sys\_eerom Ver. 3, 2014/11/14

#### 3.0 Test Completion

- Engineering Integration Tests (EIT)
   EIT Completed on 2016/09/13
- 2. NTC Tests 1> NA

## 4.0 Software/Firmware Fixes, Changes, and Enhancements

The \* mark indicates engineering items.

#### 1. ONIE Installer

# Ver. 2015.05.00.06, 2016/09/19

1 First version of ONIE v2016.08; uboot was modified.

## Ver. 2015.05.00.06, 2015/11/03

1 First version of ONIE v2015.05

## Ver. 2015.02.00.05, 2015/06/05

1 First version of ONIE v2015.02

## Ver. 2014.11.00.03, 2015/01/21

Ī	1	First version of ONIE v2014.11	
Ī	2	Added enhancement to erase mass storage in uninstall mode	
Ī	3 Removed mkfs.ext3 from ONIE due to the size of the ONIE version		

# Ver. 2014.08.00.13, 2014/11/14

1	ONIE updater writes the value of "0x29 ONIE Version" in sys_eeprom, and "ver" in uboot
	environment during updating process.
2	Supports kernel module insertion

# Ver. 2014.08.00.08, 2014/09/29

1 Increased the expire time for management port negotiation to 10 seconds

## Ver. 2014.08.00.05, 2014/09/11

1	Upgraded to ONIE v2014.08	
2	Changed to use the standard naming in machine.conf:	
	onie_platform changed to powerpc-accton_as5610_52x-r0 from powerpc-as5610_52x	
	onie_machine changed to accton_as5610_52x from as5610_52x	
3	Made the v2014.08.00.05 updater flexible to allow to update from the pre-v1.6.1.4 with old	
	onie_platform "powerpc-as5610_52x" and the post-v2014.08 with new onie_platform	
	"powerpc-accton_as5610_52x-r0"	

## Ver. 2014.08.00.04, 2014/08/15

1*	Upgraded to ONIE v2014.08, onie_platform=powerpc-accton_as5610_52x-r0,	
	onie_machine=accton_as5610_52x	
2*	This version was built for internal ONIE certification test	
3	Removed mkfs.ext3 from ONIE for image size concern. mkfs.ext3, if needed, should be	
	loaded in the switch software installer.	

## Ver. 1.6.1.4, 2013/11/11

1	Added ONIE updater that accepts three different machine names, accton_5652, es5652bt2-flf-zz, and as5610_52x
2*	Bug fix: ONIE still fetches the default installer filenames even DHCP option 66 and 67 are provided
3*	Bug fix: ONIE still fetches the default installer filenames even DHCP option 150 and 67 are

## ENGINEERING RELEASE NOTES – ACCTON COMPANY CONFIDENTIAL

n	ra	/1/	40	М
ν	ro	VΙ	ᄺ	u

#### Ver. 1.6.1.3. 2013/10/17:

1	Added mkfs.ext2
2*	change MACHINE to as5610_52x, no VENDOR_REV

## Ver. 1.6.1.0, 2013/10/04

4	1 141 1	
1 1	Initial	VACCION
	1 111111111111	version

#### 2. Bootloader

## Ver. 3.0.3.13, 2016/09/19

1	Optimized DDR parameter settings
2	For ONIE v2016.08.00.02 build

# Ver. 3.0.3.12, 2015/11/03

1 For ONIE v2015.05.00.06 build.

#### Ver. 3.0.3.11, 2015/06/05

1 For ONIE v2015.02.00.05 build.

## Ver. 3.0.3.10, 2015/03/05

1 For ONIE v2014.11.00.04 build.

#### Ver. 3.0.3.9, 2015/01/21

1 For ONIE v2014.11.00.03 build.

## Ver. 3.0.3.7, 2014/11/14

1 Enhanced in the u-boot built with ONIE 2014.08.00.12:
Accton powerpc platforms: Sync u-boot environment to latest code.

#### Ver. 3.0.3.6, 2014/03/20

1 Changed the default value of environment variables, platform=accton\_as5610\_52x and onie\_platform=powerpc-accton\_as5610\_52x-r0, to be consistent with ONIE v2014.08.

## Ver. 3.0.3.5, 2014/03/20

1	Diag LED to light green if no error caught
2*	Fixed "Waiting for D_INIT timeout. Memory may not work" message

## Ver. 3.0.3.4, 2013/12/09

1 Changed default of uboot environment: adding "platform" automatically in uboot environment if it does not exist

#### Ver. 3.0.3.3, 2013/11/27

1	Changed environment variable "platform" to value as5610_52x	
2	Changed the default fan speed to full speed	
3*	Updated the value of environment variable "ver" to flash	
4*	Fine tuned the speed of accessing external USB to be compatible with more USB disks to	

#### ENGINEERING RELEASE NOTES - ACCTON COMPANY CONFIDENTIAL

## Ver. 3.0.3.0, 2013/10/15

1\* Added DRAM test command for production test purpose

# Ver. 3.0.2.0, 2013/10/02

1*	Corrected output message: ES5652BT1 to ES5652BT2
2*	Fixed DDR output message

## Ver. 3.0.0.0, 2013/09/25

4	1 141 1	
1 1	Initial	version
	HHILIAI	VC131011

# 3. Diagnostic

## Ver. 1.0.0.0, 2015/01/29

1 Adjusted the burn-in test items

## Ver. 0.0.0.13, 2015/01/29

1 Added mkfs.ext3 to Diag installer for the command removal from ONIE v2014.11.

## Ver. 0.0.0.12, 2014/10/08

1 Fixed Diag version number display in v0.0.0.11

# Ver. 0.0.0.11, 2014/10/06

1	Added test items,
	test m 20160100: to check USB controller firmware version and date
	test m 20160200: to set NAND type to "Hard Disk"

## Ver. 0.0.0.10, 2014/06/11

1	Applied the new rc.soc	
2*	Applied the new burn-in loopback traffic test criteria	
3*	Fixed burn-in bug: port loopback OK but reported error.	

## Ver. 0.0.0.9, 2014/04/09

4	1 1 1 1 1 1 1	
1	I Improved the burn-in error lo	$\sim$
	1 1111010VEC 1NE DITINEIN ENOUG	)( 1

## Ver. 0.0.0.7, 2013/12/06

1*	judged PSU air flow by reading EEPROM "4M1" as front to back and "4M2" as back to front
2*	Removed fan test from burnin.

# Ver. 0.0.0.6, 2013/11/29

1*	Corrected PSU test
2*	Implemented for 40G single loopback burnin test: adding 40G specific setting in the rc.soc
	that is only used when Diag enters burnin mode.

## Ver. 0.0.0.5, 2013/11/11

## ENGINEERING RELEASE NOTES - ACCTON COMPANY CONFIDENTIAL

1 Initial version

# 4. sys\_eeprom

## Ver. 3, 2014/11/14

I	1	Added "0x28 Manufacturer=Accton", "0x2C Country Code=TW", "0x2D Vendor
		Name=Edgecore" and "0x2E Diag Version"

## Ver. 2, 2014/09/11

1	Added 0x28 Platform Name "powerpc-accton	205710 52v r0"
1 1	Added 0x26 Platform Name DowerDC-accton	asorio ozx-io

# Ver. 1, 2014/01/13

4	1 141 1	
1	Initial	version
	1111111111111	VEISION

#### 5.0 Known Limitations & Workarounds

Because the onie\_platform string was modified since v2014.08, there is no support for direct upgrade from the old v1.6.1 to versions later than v2014.08. Please use v2014.08 as intermediate version and upgrade to v2014.08 before further upgrade.