AS4610-30P, AS4610-30T Data Center Switch Release Note Version 2016.05.00.03-2016.07.27.00

1.0 Introduction

2.0 Release Content

- 1. ONIE Installer Ver. 2016.05.00.03, 2016/07/27
- 2. Bootloader Ver. 2012.10.0.3, 2016/07/27
- 3. Diagnostic Ver. 001.6, 2016/07/15
- 4. sys_eerom Ver. 2, 2015/09/01

3.0 Test Completion

- Engineering Integration Tests (EIT)
 EIT Completed on 2016/01/04
- 2. NTC Tests 1> NA

Page: 1 of 6 Accton Confidential

4.0 Software/Firmware Fixes, Changes, and Enhancements

The * mark indicates engineering items.

1. ONIE Installer

Ver. 2016.05.00.03, 2016/07/27

Based on ONIE 2016.05 that has "arm-iproc: invalidate d-cache before booting a kernel" fix in uboot

Ver. 2016.05.00.01, 2016/06/30

1 Based on ONIE 2016.05 that has uboot grub snapshot function

Ver. 2015.11.00.01, 2016/01/04

1	Based on ONIE 2015.11	
2	2 Enlarged size of sys_eeprom	
3	3 Fixed no i2c slave device found by i2cdetect	

Ver. 201508292210, 2015/09/01

1	Initial version		

2. Bootloader

Ver. 2012.10.0.3, 2016/07/27

1 Based on ONIE 2016.05 that has "arm-iproc: invalidate d-cache before booting a kernel" fix in uboot

Ver. 2016.05.00.01, 2016/06/30

1 Based on ONIE 2016.05 that has uboot grub snapshot function

Ver. 2012.10.0.1, 2016/01/04

1 Enlarged size of sys_eeprom

Ver. 2012.10-ga1b2001, 2015/09/01

1 Initial version

3. Diagnostic

Ver. 001.6, 2016/07/15

1	Modify LED bit stream to be able to compatible with 2 nd source chip	
2	Modify to support flexible burnin items	

Ver. 001.4. 2015/09/01

1	Initial version	l	

ENGINEERING RELEASE NOTES – ACCTON COMPANY CONFIDENTIAL

4. sys_eeprom

Ver. 2, 2015/09/01

1 Initial version

5.0 Known Limitations & Workarounds

Subject to Change Without Notice