

**AS4600-54T**  
**Data Center Switch**  
**Release Note Version 2014.08.00.10-2014.12.08.00**

### 1.0 Introduction

AS4600-54T consists of 48 10/100/1000 Base-T ports with additional 4 10 Gigabit SFP+ ports. There are two optional expansion modules which supports 2\*40G stacking or uplink ports on the rear panel. The management port on the front panel can be used to download the software.

### 2.0 Release Content

1. **ONIE INSTALLER VER. 2014.08.00.10, 2014/10/23**
2. **BOOTLOADER VER. 3.0.1.8, 2014/09/02**
3. **DIAGNOSTIC VER. 0.0.0.15 2013/12/12**

### 3.0 Test Completion

1. **Engineering Integration Tests (EIT)**  
1> EIT Completed on 2014/10/24
2. **NTC Tests**  
1> NTC Completed on 2014/12/08

### 4.0 Software/Firmware Fixes, Changes, and Enhancements

#### 1. ONIE Installer

##### Ver. 2014.08.00.10, 2014/10/23

1	Added support for inserting kernel modules for updaters and installers running on 2014.08.00.10 or later, to do CPLD update.
2	Added support for writing "sys_eeprom" for updaters and installers running on 2014.08.00.10 or later, to update "sys_eeprom". Also, implemented (starting from 2014.08.00.10) actually updating "sys_eeprom" when running on ONIE which supports doing this (2014.08.00.10). This means that if you are running 2014.08.00.08, you need to update first to 2014.08.00.10 to support writing "sys_eeprom", and then, while running ONIE 2014.08.00.10, run the installer for 2014.08.00.10 again to actually update the "sys_eeprom".
3	Changed all partitions to read/write, so that, in the future, e.g., RCW may be updated via ONIE.
4	Disabled the driver for PHY interrupts, so that for hardware versions R01D and later (e.g. R01E), the management port can link up in ONIE.

##### Ver. 2014.08.00.08, 2014/09/24

1	Increased the time-out when ONIE starts when waiting for autonegotiation of the management port.
---	--

**Ver. 2014.08.00.05, 2014/09/02**

1	Upgraded to ONIE v2014.08.
2	Changed to use the standard naming in /etc/machine.conf: onie_platform=powerpc-accton_as4600_54t-r0 onie_machine=accton_as4600_54t
3	Made the v2014.08.00.05 updater flexible to allow to update from the v1.6.1.6 or earlier with old onie_platform "powerpc-as4600_54t-r0" and the v2014.08 or later with new onie_platform "powerpc-accton_as4600_54t-r0".

**Ver. 1.6.1.5, 2013/11/11**

1	adding ONIE updater that accepts three different machine names, accton_4654, ees4654bf-flf-zz, and as4600_54t
2	bug fix: (ONIE)ONIE still fetching the default installer filenames even DHCP option 66 and 67 are provided
3	bug fix: (ONIE)ONIE still fetching the default installer filenames even DHCP option 150 and 67 are provided

**Ver. 1.6.1.4, 2013/10/24**

1	add mkfs.ext2
2	change MACHINE to as5610_52x, no VENDOR_REV

**Ver. 1.6.1.3, 2013/10/04**

1	add mkfs.ext2
---	---------------

**2. Bootloader****Ver. 3.0.1.9, 2014/10/23**

1	Updated the default ONIE version number (2014.08.00.10) inside u-boot.
---	--

**Ver. 3.0.1.8, 2014/09/02**

1	Changed the default value of environment variables to be consistent with ONIE v2014.08: platform=accton_as4600_54t onie_platform=powerpc-accton_as4600_54t-r0
---	---

**Ver. 3.0.1.7, 2014/03/20**

1	to correct lighting of Diag, PSU, FAN, and Module LEDs
2	fixed "Waiting for D_INIT timeout. Memory may not work" message

**Ver. 3.0.1.6, 2014/01/10**

1	force LED2 (54616S INIT_L) to high
2	improve coding style

**Ver. 3.0.1.5, 2013/12/09**

1	auto create "platform" in uboot environment if it does not exist
---	--

**Ver. 3.0.1.4, 2013/11/27**

1	add environment variable "platform" with value as4600_54t
2	update the value of environment variable "ver" to flash

3	change the default fan speed to full speed
---	--

**Ver. 3.0.1.2 2013/11/08**

1	Linux kernel with 0x2000 (2KB) uboot environment size will be forced to use size 0x10000 (64KB) when boot up
2	fine tune the speed of accessing external USB to be compatible with more USB disks to read big files

**Ver. 3.0.1.1, 2013/10/17**

1	Fixed the second usb start failure problem
---	--

**Ver. 3.0.0.1, 2013/10/04****3. Diagnostic****Ver. 0.0.0.15, 2013/12/25:**

1	fix redundant print message when checking only one PSU.
---	---

**Ver. 0.0.0.14, 2013/12/18:**

1	correct the test item for PSU FAN direction
---	---

**Ver. 0.0.0.12, 2013/11/11:**

1	initial version
---	-----------------

**4. sys\_eeprom****Ver. 5, 2014/11/19**

1	Updated to remove some need for Production Test to write.
2	Added more non-blank default values.

**Ver. 4, 2014/10/24**

1	Changed 0x29 ONIE version from "2014.08.00.08" to "2014.08.00.10".
2	Added more default values.

**Ver. 3, 2014/09/26**

1	Changed 0x29 ONIE version from "2014.08.00.05" to "2014.08.00.08".
---	--

**Ver. 2, 2014/09/05**

1	Changed 0x28 Platform Name from "powerpc-as4600_54t-r0" to "powerpc-accton_as4600_54t-r0".
---	--

**Ver. 1, 2013/11/04**

1	Initial version.
---	------------------

**5.0 Known Limitations & Workarounds**

**None**